

Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Plastic enclosure type A and base type a



Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Plastic enclosure type A and base type a




Plastic enclosure type B and base type b



Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Plastic enclosure type B and base type b




Plastic enclosure type C and base type c



Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Plastic enclosure type C and base type c




Base type d




Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Metal enclosure type A



Metal enclosure type A




Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Metal enclosure type A




Internal side of plastic enclosure type A



Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Metal enclosure type B





Metal enclosure type B




Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Metal enclosure type B




Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001


Internal side of plastic enclosure type C




Power supply with DC/AC inverter board type PWPC1742



Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001




Main board and audio board type A




Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Main board and audio board type B




Main board and audio board type B




Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Main board type C




Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

Key control board type 715G1663



Key control board type 715G1663



Type Designation: L174F1 (NEC, MITSUBISHI)
Report Number: 11006763 001

